


# PFP



## Punte a forare in HW integrale

Solid HW drills

VHW-Bohrer



| CODICE    | D   | L  | Lu | S   | Rot. |
|-----------|-----|----|----|-----|------|
| PFPD-0200 | 2   | 49 | 25 | 2   | RH   |
| PFPD-0250 | 2.5 | 57 | 27 | 2.5 | RH   |
| PFPD-0300 | 3   | 55 | 27 | 3   | RH   |
| PFPD-0320 | 3.2 | 52 | 27 | 3.2 | RH   |
| PFPD-0350 | 3.5 | 52 | 27 | 3.5 | RH   |
| PFPD-0400 | 4   | 55 | 27 | 4   | RH   |
| PFPD-0450 | 4.5 | 58 | 28 | 4.5 | RH   |
| PFPD-0500 | 5   | 62 | 28 | 5   | RH   |
| PFPD-0600 | 6   | 62 | 28 | 6   | RH   |
| PFPS-0200 | 2   | 49 | 25 | 2   | LH   |
| PFPS-0250 | 2.5 | 57 | 27 | 2.5 | LH   |
| PFPS-0300 | 3   | 55 | 27 | 3   | LH   |
| PFPS-0320 | 3.2 | 52 | 27 | 3.2 | LH   |
| PFPS-0350 | 3.5 | 52 | 27 | 3.5 | LH   |
| PFPS-0400 | 4   | 55 | 27 | 4   | LH   |
| PFPS-0450 | 4.5 | 58 | 28 | 4.5 | LH   |
| PFPS-0500 | 5   | 62 | 28 | 5   | LH   |
| PFPS-0600 | 6   | 62 | 28 | 6   | LH   |