

112

Sgorbie per torni automatici

Gouges for automatic lathes

Hohleisen für Automatendrehbank




HSS
Cob.5%

TANTUNG

C40



ON
REQUEST



CODICE	B	H	L	R	Tipo	Materiale
112-1-18-H	20	30	180	0.5	H	HSS-Co
112-1-20-H	20	30	200	0.5	H	HSS-Co
112-1-22-H	20	30	220	0.5	H	HSS-Co
112-1-25-H	20	30	250	0.5	H	HSS-Co
112-1-18-T	20	30	180	0.5	T	Tantung
112-1-20-T	20	30	200	0.5	T	Tantung
112-1-22-T	20	30	220	0.5	T	Tantung
112-1-25-T	20	30	250	0.5	T	Tantung
112-2-18-H	20	30	180	1	H	HSS-Co
112-2-20-H	20	30	200	1	H	HSS-Co
112-2-22-H	20	30	220	1	H	HSS-Co
112-2-25-H	20	30	250	1	H	HSS-Co
112-2-18-T	20	30	180	1	T	Tantung
112-2-20-T	20	30	200	1	T	Tantung
112-2-22-T	20	30	220	1	T	Tantung
112-2-25-T	20	30	250	1	T	Tantung
112-3-18-H	20	30	180	2	H	HSS-Co
112-3-20-H	20	30	200	2	H	HSS-Co
112-3-22-H	20	30	220	2	H	HSS-Co
112-3-25-H	20	30	250	2	H	HSS-Co
112-3-18-T	20	30	180	2	T	Tantung
112-3-20-T	20	30	200	2	T	Tantung
112-3-22-T	20	30	220	2	T	Tantung
112-3-25-T	20	30	250	2	T	Tantung
112-4-18-H	20	30	180	4	H	HSS-Co
112-4-20-H	20	30	200	4	H	HSS-Co
112-4-22-H	20	30	220	4	H	HSS-Co
112-4-25-H	20	30	250	4	H	HSS-Co
112-4-18-T	20	30	180	4	T	Tantung
112-4-20-T	20	30	200	4	T	Tantung
112-4-22-T	20	30	220	4	T	Tantung
112-4-25-T	20	30	250	4	T	Tantung