

G

Sgorbie per torni automatici

Gouges for automatic lathes

Hohleisen für Automatendrehbank

HSS
Cob.5%

ON
REQUEST



CODICE	B	H	L	R	Profilo
G1	20	25	240	4	L
G2	20	25	240	4	V
G3	25	25	240	6	L
G4	25	25	240	6	V
G5	25	30	240	12	L
G6	25	30	240	6	L
G7	25	30	240	6	V
G8	30	30	240	12	L
G9	30	30	240	12	V
G10	25	25	240	5	L
G11	25	25	240	5	V
G12	25	30	240	5	L
G13	25	30	240	5	V
G14	30	30	240	8	L
G15	30	30	240	8	V
G16	30	30	240	6	L
G17	30	30	240	6	V

